



Day (25 -Jun-2009)

MachineName	Good Parts	Defect Parts	OEE	Availability	Performance	Quality
AssemblyMC1	65395	485	37%	37%	100%	99%
AssemblyMC2	16405	324	49%	75%	66%	98%
Filler_manual	11000	350	83%	92%	93%	97%
Total:	92800	1159	65%	73%	90%	98%